

Data Charts

Andrew_Longworth to: Forrest.Sabrina

11/30/2010 02:48 PM

From: Andrew_Longworth@URSCorp.com

To:

Cc: Megan_Dudevior@urscorp.com

Sabrina,

I was digging through some data/reports here and found something to explain the 1999 jump in concentrations. It turns out that between 1996 and 1999 water from cement creek above American Tunnel was treated then between 2002 and 2003 water from Gold King was treated. The charts I provided were based on treatment stopping in 2003 and did not take into account the switch between the two. I found this information in the Stanley Church 2007 "The effects of acidic mine drainage from historical mines in the Animas River watershed, San Juan County, Colorado" report.

Thanks,

ANDREW LONGWORTH

URS OPERATING SERVICES, INC.

1099 18th Street, Suite 710

Denver, Colorado, 80202

Tel: (303) 291-8248

Cell: (720) 810-0780

Fax: (303) 291-8296

Andrew_Longworth@URSCorp.com

This e-mail and any attachments contain URS Corporation confidential information that may be proprietary or privileged. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information and you should destroy the e-mail and any attachments or copies.

Forrest.Sabrina@epamail.epa.gov

11/23/2010 02:43 PM

To Andrew_Longworth@URSCorp.com

cc Megan_Dudevior@urscorp.com, Way.Steven@epamail.epa.gov

Subject Re: Updated Cd and new Cu

Thanks for compiling those for us! We will be building on those for future conversations with the community.

Sincerely,

Sabrina Forrest

NPL Coordinator &

Site Assessment Manager

U.S. Environmental Protection Agency

1595 Wynkoop Street, Mail Code: 8EPR-B

Denver, CO 80202-1129

Direct Ph: 303-312-6484

Toll Free: 1 800-227-8917, 312-6484

Fax: 303-312-6065

Agency Cell: 303-589-1286

E-mail: forrest.sabrina@epa.gov

NOTICE: The information contained in this e-mail is intended only for the use of the recipient(s) named above. This message and any attachments may contain confidential or privileged information. If the reader is not the intended recipient or an agent responsible for delivering it to the intended recipient, you have received this document in error and any review, dissemination, disclosure, distribution, use, or copying of the contents of this message is strictly prohibited. If you have received this communication in error, please notify me immediately by e-mail or telephone and destroy all copies of the original message and any attachments.

From: Andrew_Longworth@URSCorp.com
To: Megan_Dudevior@urscorp.com, Sabrina Forrest/R8/USEPA/US@EPA
Date: 11/23/2010 01:37 PM
Subject: Updated Cd and new Cu

Thanks,

ANDREW LONGWORTH
URS OPERATING SERVICES, INC.
1099 18th Street, Suite 710
Denver, Colorado, 80202
Tel: (303) 291-8248
Cell: (720) 810-0780
Fax: (303) 291-8296
Andrew_Longworth@URSCorp.com

This e-mail and any attachments contain URS Corporation confidential information that may be proprietary or privileged. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information and you should destroy the e-mail and any attachments or copies.

[attachment "CadmiumCC48A72A68Linear.pdf" deleted by Sabrina Forrest/R8/USEPA/US] [attachment "CopperCC48A72A68Linear.pdf" deleted by Sabrina Forrest/R8/USEPA/US]